

# Installation manual for standing softbox

## A. Parts numbers and quantity

### 1. Aluminum Poles

P1:3pcs

P2:6pcs

P3:3pcs

P4:6pcs

P5:3pcs

### 2. Connectors and bolt

B1:3pcs

B2:3pcs

B3:2pcs

B4:6pcs(Already mounted to pole)

H1:2pcs

### 3. Wheels , hexagon- screws and hexagon spanner

Wheel:3pcs

Srews:23pcs


Spanner:1pc

### 4. Black reflecting covers and with disffuser





## B. Setting step by step

1. Connect P1 to P5 with B4&screws,. Connect P3 to P5 with B4&screws/(3sets)



2. Connect 3pcs P4 with 3pcs B2&screws in a triangle, make the tops and bottoms of B2 stay same
3. Connect 3pcs P4 with 3pcs B1&screws in a triangle, make the tops and bottoms of B1 stay same
4. Connect 3pcs P2 to B3/(2sets)



5. Connect T1 (put it at the bottom) to P154with 3wheels
6. Connect T2 (put it at the top) to P154 with screws
7. Connect P222 to P154 with screws
8. Put H1 into B3 and secure it with screws
9. Put on the black cover from bottom to top and cover the from with the white disffuser

## B. Using

1. Put lightings on the bolt (H1), H1 can be fixed both tops to fit for different types of lightings
2. Lighting wire go out from corner holes or from the side windows

